


# POČTY OPOTŘEBITELNÝCH NÁHRADNÍCH DÍLŮ


ROW-MASTER		RN 4800	RN 6400	RN 9600	RN 3000 S	RN 6000 S	RN 9000 S
Soc 150 mm	pcs	25–31	34–38	55–61	19	37	55
Soc 40 mm	pcs	7–9	16–24	22–36	12	24	36
Soc 60 mm	pcs	12–16	9–13	12–19	7	13	19
Disque de protection	pcs	12–16	16–24	22–36	12	24	36
Bouclier solide	pcs	12–16	16–24	22–36	12	24	36
Peignes de herse 10 mm	pcs	16–22	24–28	34–37	12	24	36
Peignes de herse 6,3 mm	pcs	—	—	—	19	37	55



## Soc 150 mm

### Modèles RN, RN\_S


- 1 – KM060310 SOC .....1 pcs
- 2 – KM000221 VIS .....1 pcs
- 3 – KM000096 ÉCROU .....1 pcs



## Soc 40 mm

### Modèles RN, RN\_S


- 1 – KM060346 SOC .....1 pcs
- 2 – KM000221 VIS .....1 pcs
- 3 – KM000096 ÉCROU .....1 pcs



## Soc 60 mm

### Modèle RN\_S


- 1 – KM060083 ÉTANÇON .....1 pcs
- 2 – KM060324 SOC .....1 pcs
- 3 – 00688162 DÉFLECTEUR .....1 pcs
- 4 – KM000616 VIS .....2 pcs
- 5 – KM000325 ÉCROU .....2 pcs
- 6 – KM000056 RONDELLE .....3 pcs



## Peignes de herse 6,3 mm

### Models RN, RN\_S


- 1 – KM210009 HERSE .....1 ks
- 2 – KM000372 VIS .....1 ks
- 3 – KM000121 RONDELLE .....1 ks
- 4 – KM000154 ÉCROU .....1 ks



## Bouclier solide

### Modèles RN, RN\_S


- 1 – 01364309 G / 00777846 D COVERING..1 ks
- 2 – KM000056 RONDELLE .....2 ks
- 3 – KM000329 VIS .....2 ks
- 4 – KM000154 ÉCROU .....2 ks



## Disque de protection

### Modèles RN, RN\_S

- 1 – KM060347 DISQUE .....1 pcs
- 2 – KM000024 RONDELLE .....12 pcs
- 3 – KM000879 VIS .....6 pcs
- 4 – KM000157 ÉCROU .....6 pcs



## Peignes de herse 10 mm

### Modèles RN, RN\_S

- 1 – KM210007 HERSE .....1 pcs
- 2 – KM000759 ÉTRIER .....1 pcs
- 3 – 00692702 RONDELLE .....1 pcs
- 4 – KM000155 ÉCROU .....2 pcs